## IN THE SPECIFICATION

Page 4, in the paragraph lines 14-18 make the following correction:

Fig. 3 further shows a diagram of the microprocessor control board 42 having a power supply 44. Each heater element 45 in the film dryer is provided with a bi-metallic temperature limiter 48. Fig. 5 shows the heater [[35]] 38, fan 39 and air duct 50 is provided with equalizing fins 52 so that there is equal air movement through the film processing tanks showing film cartridges mounting X-ray film 54.